## Maintenance & Repairs

01/10/24	General Description
01/10/24	
	Replaced LBCU (Light Bar Control Unit) in the dash (indicator lights and such). The LCD display was beginning to fail. The LCD component is not serviceable on its own so the entire control unit was replaced.
	Replaced Propane Detector With Propane & CO2 Detector (Old Propane Detector Aged Out, The Exact Model Was No Longer Available)
08/27/23	Change Oil / replace oil filters (Engine & GenSet) ODO: 26,746
	Replaced All Smoke & CO2 Detectors Due To Age Had Tow Braking System Updated / Changed To AirForce One Braking System Due To New Car
05/01/23	Replaced Main TV With Newer Model For Streaming, APPs, Etc. Replace Both Front Chairs: Had Pilot and Co-Pilot Chairs Replaced. Dave & LJs RV Interior Design: Dilly
	Captains Charis (443) With Arms, Skirt, Ultra Leather, Color: Saddle (matchs the recliners they installed a few years ago). Installed on existing power units.
	Serviced TPMS Senders: Cleaned, replaced battieries, replaced o-rings on the tow sensors.  Replaced windsheild washer pump. Purchased unit via Amazon
	Normal Engine Service & Normal Genset Service:
	$\label{eq:continuous} Oil Filters, Fuel Filter, Oil (Mobile DELVAC 15W40) for both engine and genset. All fluids, brakes, suspension ok. \\$
12 /02 /21	Replaced Tires (Aged Out)
	6 - 275/70R22.5 Michelin XMZ Tires: DOT 2721 [27th week of 2021). Added Rear Valve Stem Kit To Ease TMPS Sender Maintenance & Tire Valve Access In General.
11/01/22	Replaced Drive Shaft On Driver Seat - Moved Seat Too Far Up Again, Stressing And Breaking Shaft. Used One Of Two Sparses, Now Just One Spars Left, 10f Purchased Three In 2017 (When It Broke For The Same Reason) For Two Extras As Part Is No Longer Available And Newmar Only Had Four Left.
	Change Oil / replace oil filters (Engine & GenSet).
06/04/21	Cleaned and Serviced All Battery Posts (Sprayed terminal battery protective sealer [red] on all terminals)
	Carrier Input / Pinion Seal Replaced. Upon inspection during normal service it was found to have begun leaking.
2021	Replaced One Kitchen Faucet Hose. (It Was Leaking).
02/26/20	eq:Replaced Dash Heater / AC Fan Motor Assembly. Purchased unit from Comfort Air (www.ComfortAirGR.com)
12/03/19	Had MoHo Washed / Waxed and Roof Treated
	By: Tucson RV Wax - Xtreme Power Washing, TucsonRvWax.com, 520.302.2322
11/01/19	Replaced Microwave
09/20/19	Replaced Cooktop Stove Sparker
09/20/19	Replaced Water Filters
09/20/19	Replaced toilet ball gasket.
	Was not holding water. Purchased two, so there is a spare one on-board the MoHo
09/12/19	Replaced Both Chassis Batteries. One chassis battery failed load test so replaced both.
	Normal Engine Service & Normal Genset Service:
09/12/19	Oil Filters, Fuel Filter, Oil (Mobile DELVAC 15W40) for both engine and genset. All fluids, brakes, suspension ok.
	$Replaced\ Gray\ \&\ Black\ Tank\ Vent\ caps.\ Put\ on\ venturi\ style\ caps\ (Cyclone).\ Old\ basic\ ones\ got\ brittle\ and\ cracked.$
12/15/18	Replaced Broken Front Door Screen Clip (That Hold Screen Up). Extra clips are in supplies bay
12/15/18	Replaced Door Swing Arm (Broken Door Stop Part).
12/15/18	Replaced Rubber Trim On Entry Steps / Floor
	Replaced Hot Water Heater Pressure Relief Valve. To Insure Hotwater Pressure Leaking Was Not Due To Faulty Valve. Less laking resulted, but it still does when air get trapped in tank from hooking up multiple times.
	Replaced Drive Shaft On Driver Seat - Purchased Three For Two Extras As Part Is No Longer Available And Newmar Only Had Four Left.
04/17/17	Replaced Water Heater Anode
11/12/16	Replaced Shower Faucet (Single Control Arm) With Faucet With Separate Hot & Cold Handles
10/16/16	Replaced Faulty Electrical Outlet In Dinette / TV Slide
	Several of the interior LED light pucks have been replaced. When one starts to flicker we generally replaced it and added easy wire connections to ease any further replacements. They are hardwired originally. There are a couple of spares on board that already have the connections added but on replacing the original ones connectors will have to be added if one wants to continue that process (other wise one can just cut and splice). The connectors are just standard insulated 12V spade connectors.
	(By Original Owners) Sewer Hose Storage Door (Small Black Door On Driver Side) Was Replaced By Original Owner. Damaged When Left Open While Operating Slide
2016	(By Original Owners) Both AC Units Were Repaired On Warranty Issues By Original Owners
2016	(By Original Owners) New House Batteries Installed By Original Owners