

Improvements

Date	General Description
2023	Added Computer Work Table - Removeable - Used When Dirver's Chair Is Turned Around
2023	Replaced Front TV With More Modern One For Streaming, APPs, Etc.
2023	Replaced Front Driver And Passenger Seats
2021	Replaced Tires (Michelin XMZ 275/70R22.5 - DOT 2721) / Valve Stems
2021	Added two USB Outlets To Dash. (Used for DashCam / GoPro but can be used for any USB powered device)
2021	Replaced Batwing TV Antenna With Digital Antenna (One With Better Weather Sealing).
2020	Replaced electrical switches for Hot Water, Security Light and Steps with lighted ones so there is a better indication of when they are on. Had to add a wire for ground (for lights in switches)
2019	Replaced as many exterior stop / clearance / turn signal light bulbs with brighter LED bulbs.
2019	Added Handle To Front Hood To Help In Opening And Lifting It. (Where GenSet Is)
2019	Added Sun Screen To Power Awning
2019	Replaced Tire Covers With Custom Made Snap On Ones
2019	Added LED Lighting To Slides (Inside)
2018	Added a small shelf to the side of one of the recliners.
2017	Added more USB and power outlets to dash area on both the driver and passenger side. Passenger side is always on. Drivers side is on with dash accessory power switch (Labeled ACC. POWER)
2017	Added Rear View Camera Monitor (That Always Has The Rear View On) and Power Switch For It. Powered By Separate Switch In Dash That Is Labeled: "2ND CAM". If that switch is not on, the monitor will still work, but will switch views with the turn signals and main camera. 2nd monitor is intended to always show rear view regardless of turn signal operation. Positioned so the passenger can aid in lane changes.
2017	Replaced Sofa With Recliners: Dave & LJ's RV Interior Design, Woodland, WA
2017	Added Chassis Battery Cutoff Switch
2017	Replaced Mattress With Sleep Number R5 Air System
2017	Added Fans & Shelf To TV Control Cabinet. It was getting hotter than we wanted, albeit said to be normal. Satellite TV DVR Unit gets very warm.
2017	Added Surge Guard Shore Power Protection. Hardwired Unit In Electrical Bay
2017	Added HDMI cable For TV. There was no HDMI cable from TV control box area above pilot's seat. Consists of two cables that should be disconnected when operating the dining table / TV slide.
2017	Added Satellite System With DVR (Dish Network)
2017	Added Storage Shelf To Shallow Storage Bay
2016	Added Tubular Store In Storage Bay. For Ladder And long Items
2016	Replaced Shower Faucet (Single Control Arm) With Faucet With Separate Hot & Cold Handles
2016	Added Outside Key Box. Inside Of Propane Door
2016	Added Water Filter. Now Have Primary And Secondary (Sediment and Treatment Stages)
2016	Replaced Shower Head